






Guida all'utilizzo dei catalizzatori Permasolid.

Zona da riparare.	 Temperatura.	Catalizzatore.
	15 - 20 °C	VHS 3220 kurz HS 3307 extra kurz HS 3309 kurz
	20 - 30 °C	VHS 3225 HS 3309 kurz HS 3310
	30 - 35 °C	VHS 3230 lang HS 3312 lang
	20 - 25 °C	VHS 3225 VHS 3230 lang HS 3310 HS 3312 lang
	25 - 30 °C	VHS 3225 VHS 3230 lang VHS 3240 extra lang HS 3310 HS 3312 lang
	30 - 35 °C	VHS 3240 extra lang HS 3315 extra lang
	20 - 35 °C	VHS 3240 extra lang HS 3315 extra lang

Queste informazioni si basano sul nostro attuale stato di conoscenza. E' possibile trovare indicazioni più dettagliate sull'utilizzo dei nostri prodotti nelle Schede Tecniche Permasolid VHS Härter 3220-3240 e Permasolid HS Härter 3307-3315.

Spies Hecker – sempre più vicina.



www.spieshecker.it

© Copyright by Spies Hecker GmbH 09/2010